

F-12G-8SDI-CWDM-TX/RX

Quick Setup Guide

- 8 Channel SD/HD 3G/12G SDI Over single fiber Transmitter/Receiver Kit

Step 1: Connect Power



Connect the included Power Supplies to the Transmitter and the Receiver



“PWR” LEDs on both units indicate that power is properly connected

Step 2: Connect Fiber




Connect Transmitter to Receiver using Single Mode Fiber with ST/PC connector (Not Included)

Distance up to 10km




“FIBER” LED on the Receiver indicates that fiber is properly connected

Step 3: Connect Inputs/Outputs



Step 4: Loop Outputs (Example)



F-12G-8SDI-CWDM-TX/RX

Quick Setup Guide



<https://thorbroadcast.com>

800-521-8467

sales@thorfiber.com